

FOR PCB INSTALLATIONS YOU WILL NEED:

- Technical ability to solder and read the wiring diagram
- +5VDC 1A power supply (regulated 5%) with a 5.5 x 2.1 x 9.5 center positive connector such as Digikey Part# T946-P5P-ND XLR

Note - by special request the Power Connector can be shipped uninstalled for custom chassis mounting OR allowing for any power supply to be soldered directly to the PCB.

- XLR connectors (5 or 3 pin) and wire
- Enclosure

Power Requirements for the DPM4 / DPM-RL and the DPM-RD Assemblies:

The DPM4 Control Board independently requires 150mA

- **DPM4 / DPM-RL** Assembly requires **300mA** (for each additional DPM-RL/COIL PCB - add 150mA)
- **DPM4 / DPM-RD** Assembly requires **200mA** (for each additional DPM-RL/SSR PCB - add 60mA)