
DS5F r1 DRILL TEMPLATE

Cut and tape this template on your chassis to use a guide. Re space the connectors and PCB as desired.



Handle the PCB with static electricity precautions - touch a grounded source to discharge static electricity before touching the PCB